


NOTE:
ALIGNMENT DEVICE TO BE LEFT
INPLACE UNTIL BACKFILL
OPERATIONS ARE COMPLETE



DATE REVISED
03/21/19

GATE VALVE BOX
ALIGNMENT DEVICE

PLATE NO.
2-03